

Howard County Traffic Signal Inspection Summary Report:

Signal Number: 085
Location: Johns Hopkins Rd. at Sanner Rd./Maple Lawn
Inspection Date: May 2, 2018

Inspection Overall Score: 16

Significant Findings:

Poles are in overall good condition. Paint coating is in good condition.



Maintenance Issues:

Several hand holes are retaining water.

