Howard County Traffic Signal Inspection Summary Report:

Signal Number: 087

Location: Lark Brown Rd. at Marie Curie Dr.

Inspection Date: May 15, 2018

Inspection Overall Score: 16

Significant Findings:

Poles are in overall good condition. There is some light rusting of the anchor bolts between the top of the foundation and the leveling nuts on the NW corner.





Maintenance Issues:

NE and SW Corners – loose tightening nuts.