

Howard County Traffic Signal Inspection Summary Report:

Signal Number: 098
Location: Guilford Rd. at Vollmerhausen Rd.
Inspection Date: May 2, 2018

Inspection Overall Score: 3

Significant Findings:

New signal.



Maintenance Issues:

None of the poles have rodent barriers.

Hazard Identification Beacon:

Newer HIB. Pole does not have a rodent barrier.

